DUNN COUNTY

Planning Unit 058: AML Printout # 87: T143N, R96W Section 5, NE, SW Planning Unit 058: AML Printout # 88: T143N, R96W, Section 5, NW, SE

Additional Legal Location: No part section

Owner:

Name:

Northern Pacific Railway Company (possibly)

Northwestern Improvement Company

Category: No data

Type: Strip (surface)

Thickness

Overburden: Coal Seam: Mined: Source:

Cultural Resource Site Number: Not formally recorded

Basic Data (excerpted from primary sources):

WCB Maps (surveys dated 1927, 1928, 1929, 1930, 1931, 1933, 1938, 1939 and 1941) indicate "strip pit - Northwestern Improvement Company...Section 5, T143N, R96W... Northern Pacific Railway Company..." No mine under the name "Northwestern Improvement Company" was listed in SEBR or CMID reports, and no additional data was noted about a mine or mines located at this Planning Unit and AML location.

Descriptive information pertaining to this mine is included in:

[source:year(pages)]

WCB Map:1927(other surveys 1928, 1929, 1930, 1931, 1933, 1938, 1939 and 1941)

Notes:

The 1927 WCB map indicates that this mine was located at T143N, R96W, Section 5; however, it does not provide a part section. Since both Planning Unit 058/AML location 87 and Planning Unit 058/AML location 88 include parts of T143N, R96W, Section 5, both have been included with this mine. It is not known if this mine was situated at Planning Unit 058/AML location 87, Planning Unit 058/AML location 88, or in some other portion of Section 5.

Sources (primary and secondary):

WCB:1927 (other surveys 1928, 1929, 1930, 1931, 1933, 1938, 1939, and 1941)